

Kubota RTV900

Parts list for Kit MCS2220

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1.	1	MCS 2220C	Computer
2.	4		M4 x 12 pan head screws
3.	4		4mm flat washers
4.	4		M4 Nyloc nuts
5.	4		8g x 3/8" self tapping screws
		<u>MCS 2222</u>	<u>Electric actuator assembly</u>
6.	1	MCS 810	Electric actuator
7.	1	MCS 2222A	actuator bracket
	3		M6 x 10 pan head screws
	3		6mm spring washers
8.	1	MCS 811A	Actuator cable
9.	2		10mm flat washers
		<u>MCS 2225</u>	<u>Throttle arm assembly</u>
10.	1	MCS 2225A	Throttle arm
11.	1		M8 allthread joiner
12.	1		M8 x 12 bolt
13.	1		8mm flat washer
14.	1	MCS 426A	Grub screw cable nipple
15.	2		M4 x 4 socket set screw (grub screw)
16.	2	BLP250	Boot Lace Pin (one spare)
17.	1	MCS 2226	Flexible cable bracket
18.	1	MCS 2221	Wiring loom
a			Computer plug
b			Cruise control fuse (5 amp)
c			Spray power relay
d			Spray power outlet plug (yellow = +ve, black = -ve)
e			Battery ground connector (black wires)
f			Spray power fuse (10 amp)
g			Battery +ve connector (red wire)
h			Neutral sensor plugs (white and red wires)
i			Brake light switch connectors (red & yellow wires)
j			Actuator plug
k			Control switch plugs
l			Speed sensor plug
m		MCS2221B	Speed sensor adaptor
19.	1	MCS 211	Control switch assembly – including;
20.	2		M4 x 12 pan head screws
21.	4		4mm flat washers
22.	2		M4 Nyloc Nuts

- | | | | |
|-----|----|--------|--------------------------------|
| 23. | 2 | | 8g x 3/8" self tapping screws |
| 24. | 1 | JD 046 | Spray power plug |
| | 2 | | 8g x 3/8" self tapping screws |
| 25. | 2 | H 3555 | Terminals for spray power plug |
| | 2 | | 2mm short arm hex keys |
| | 10 | | 150mm cable ties |
| | 10 | | 200mm cable ties |

Installation Instructions (including warranty sheet)
 Operating Instructions
 Trouble shooting guide

Parts list drawing

